

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

BY377  
NNE  
1/2-1  
0.613 mi.  
3238 ft.

MANHOLE #72976  
AVE Y & W 3RD STREET  
BROOKLYN, NY

NY Spills S104283437  
N/A

Site 1 of 2 in cluster BY

Relative:  
Higher

Actual:  
14 ft.

SPILLS:

Name: MANHOLE #72976  
Address: AVE Y & W 3RD STREET  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9909099 / 2003-06-17  
Facility ID: 9909099  
Facility Type: ER  
DER Facility ID: 73827  
Site ID: 79519  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 1999-10-27  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 1999-10-27  
CID: 201  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1999-10-27  
Spill Record Last Update: 2003-06-26  
Spiller Name: CALLER  
Spiller Company: CON ED  
Spiller Address: 4 IRVING PL  
Spiller Company: 001  
Contact Name: CALLER  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was

O'CONNELL E2MIS 128666 J.FRANCO#62588 OF FOD REPORTS FOUND 1-PINT OF DIELECTRIC FLUID FROM FEEDER 7B53 ON 300 GALLONS OF WATER IN MANHOLE 72976. MR FRANCO FOUND THIS SPILL WHILE SHOOTING FAULT ON FEEDER 7B53. SPILL APPEARS TO BE CONTAINED AT THIS TIME. NO SEWERS OR WATERWAYS AFFECTED. SAMPLE TAKEN & E.S.TAG#15037 PLACED. CLEANUP PENDING TEST RESULTS. NO PARKING 11:00 - 1:00 THURSDAY. D.HERBST 27461 10/27/99--0835HRS--LAB RESULTS RETURNED <1.PPM SEQ#99-11313 UPDATE\*\*\*\*\* 10-27-99 22:00HRS C. LUGO REPORTS, CLEANUP COMPLETED & TAG removed.. S.PACE 49874. CLEANUP COMPLETED USING BIO-GEN 760. INCIDENT IS CLOSED. TJ - 50495 \* Update - No leaking company equipment - H bertorelli # 54348 UPDATE 1/20/03 REVIEW OF RECORDS SHOW FDR WAS REPAIRED ON OCT. 28, 1999 EV"

Remarks: "FEEDER LINE FAILED. REPAIR HAS NOT BEEN MADE. LEAK HAS BEEN STOPPED IN 300 GLS OF WATER CON ED #128666"

All Materials:

Site ID: 79519  
Operable Unit ID: 1087793  
Operable Unit: 01

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material ID: 298194  
Material Code: 0541A  
Material Name: dielectric fluid  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported